



A

L=Ø6.5x32

8X



B

L=Ø15x12

8X



C

L=Ø6x30


8X



D

L=Ø8x40

8X



E

L=33x33x20

4X



F

L=M4x14

44X



G

L=M4x16

6X



H

L=M4x25

2X



I

L=M4x35


11X



J

L=M3x18


8X



K

L=17x16x11


8X



L

L=108x62x35

2X



M

L=108x62x35

4X



N

L=Ø6x12

12X



O

L=Ø25x0.4

8X



P

L=M8x20


16X



Q

L=Ø17xØ8x1.5


16X



R

L=5MM


1X



S

L=20*1.5*200MM


2X



T

L=Ø6x25

2X




U


L=Ø12*Ø4*1.5

4X


TOOLS NOT INCLUDED




1




2




3




4




5




6




7




8




9




10




11



12



13



14

